Service No.

Address 17 Gleason Road

Lexington 73, Mass.

Location 47 Gleason Road

Kind of Pipe Com. June 1, 1948

Size

Size of Main

Repairx Renavalx New Service

Location

NAME AND A SELECTION OF THE SELECTION OF				Location							
Date		Material	Amount		Total		Date			Amount	
pr. 9.1	48	Labor	45	95			april 2	48	Defouted	125	00
10		11			51	02	June 3	48	Elfunded	22	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		10% Overhead			5	10	0			102	80
	ļ. !	50' - 6" Sewer Pi	pe @.26	<u>;</u>	13	00					
·	ļ!	1 - 6" Elbow			1	18			27 S		·
· · · · · · · · · · · · · · · · · · ·	<u> </u>	Joint Compound			3	00					
		Littlefield Shove	1 3 hrs	.@7	00 ' 21	00					<u> </u>
		Trucking 2 hrs.	₽.75		<u> </u>	50					-
· ·		Patching 12 x 3			12	00			* ************************************		L
					107	80			.		<u> </u>
		Labor									
		i em granjese na	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						Service Comments and Service C		
LID CA11					11						

TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS

SEWER DIVISION

DATE	NO												
The undersigned applies for the construction of a particular sewer connecting No													
Am't of estimate \$													
Am't Paid \$													
	••••••••••	Owner											
Sketch of Service Here													
		•											
	 												
		•											
	 												
	╎╌╏╏╏╏╏╏╏╏╏												
		•											
		• •											
		•											
Connection made in	Street. Work completed												