

Name **George Selfridge**Service No. 54 **1103**Address **5 Gleason Road**Location **5 Gleason Road**

Kind of Pipe

Size

Size of Main

~~REPAIR WORK~~ **New Service**

Location

Date	Material	Amount	Total	Date		Amount
Oct. 27, '47	Labor	33 80	33 80	10/27/47	Deposited	85 00
	10% Overhead		3 38	12/31/47	Refunded	19 17
	50' - 6" Sewer Pipe @.26		13 00			65 86
	1 - 6" - 1/4 Bend		1 18			
	Joint Compound		3 00			
	Trucking 2 hrs. @.75		1 50			
	Patching 10 x 3		10 00			
			65 86			
	Labor					
	Com. 12/31/47					

