

Name ~~Irish~~ Ward

Service No. 16

Address 63 Gleason Road

Lexington, Mass.

Location 63 Gleason Road

Kind of Pipe Com. June 2, 1948

Size

Size of Main

~~Repair~~ ~~Renewal~~  New Service

Location

Date	Material	Amount	Total	Date		Amount
Mar. 31, '48	Labor	95		Mar 29 48	Deposited	125 00
Apr. 1, '48	"	<u>31 37</u>	32 32	June 3 48	Refunded	<u>21 31</u>
	10% Overhead		3 23			103 69
	52' - 6" Sewer Pipe @.26		13 52			
	Joint Compound		3 12			
	Littlefield Shovel 5 hrs. @ 7.00		35 00			
	Trucking 2 hrs. @.75		1 50			
	Patching 15 x 3		<u>15 00</u>			
			103 69			
	Labor					
				10/14 67	Roots	
				4/27/72	Roots 10' Out	

