

Name William R. Hayes

Service No. 198

Address 85 Gleason Road

Lexington, Mass.

Location

Kind of Pipe

Size

Size of Main

~~Repair/ Renewal~~ New Service

com. 12-31-51

Location

Date	Material	Amount	Total	Date	Amount
12/4/51	Labor	37 18		11-26-51	Deposited 150 00
	10% overhead	3 72	40 90	12-31-51	Refunded (55 13)
	36' - 6" sewer pipe @ .342		12 31		94 87
	joint compound		2 16		
	4 hrs. Littlefield shovel		28 00		
	2 hrs. trucking		1 50		
	patching 10 x 3		10 00		
			94 87		
	Labor			11/10/51	Paper

