Service No.

Address 91 Gleason Road

Lexington 73, Mass.

Location 91 Gleason Roa d

	Kind of Pipe Com. June 1, 1948							Size of Main				
Kepaix-Renewal—New Service							Location					
Date		Material	Amount		Total		Date			Amount		
Apr. 2	2 1/18	Labor	112	67			april 13	48	Deforted	125	00	
2		11	1),	35	57	02	June 3	148	Capinded	19	1/2	
		10% Overhead			5_	70	0			105	58	
		48' - 6" Sewer P	pe @.26		12	48					<u> </u>	
		Joint Compound			2	88	· .					
		Littlefield Shove	1 2 hrs	•	14	00						
		Trucking 2 hrs.	.75		1	50						
		Patching 12 x 3			12	00						
					105	58						
		Labor										
					. 10 /80 1 4. 11		See . In P					
-											T	
						1		1				
TTD (411	-		 		 	+	#	+	 	 	+	

TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS

SEWER DIVISION

DATE	NO												
The undersigned applies for the construction of a particular sewer connecting No													
Am't of estimate \$													
Am't Paid \$													
Sketch of Service Here													
Connection made in	treet. Work completed												
Remarks:													