

Name M. J. Crowley

Service No. 85

Address 43 Grape Vine Avenue

Lot # 66

Location

Kind of Pipe

Size

Size of Main

~~Repair or Renewal~~ — **New Service**

COM. 8-30-54

Location

Date	Material	Amount	Total	Date	Amount
7/14/54	Labor	40 63		6-2-54 Deposited	125 00
	10% Overhead	<u>4 06</u>	44 69	8-30-54 Refunded	<u>(29 37)</u>
	54'-6" Sewer Pipe @.30		16 20		95 63
	Joint Compound		3 24		
	1 Hrs. Littlefield Shovel @ 7.50		30 00		
	2 Hrs. Trucking @.75		<u>1 50</u>		
			95 63		
	Labor				

