



Address	Map and Lot	Permit Number	Contractor Name	Inspector
30 Grassland St	33-69	5866	Bradley Landscaping	dpavlik msprague
Date	Material	Depth of Cover	Amount	
9/15/2014	6x6 AC to PVC Fern Co		1-Connect to existing stub	
	6" PVC Pipe - SDR 35		58 ft to 45 degree bend	
	45 degree PVC Bend		1	
	6" PVC Pipe - SDR 35		10 ft to Fern Co	
	4" x 6" PVC Fern Co		1	
Type of work completed				

New 6" PVC sewer service installed to new house, connection to existing stub.