

Name Benjamin Franklin Homes

Service No. 64

Address 5 Grove Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service

Location *Comm 2-17-61*

Date	Material	Amount	Total	Date	Amount
6-8-61	Labor 66.72			5-31-61	Deposit 200 00
6-10-61	Labor 55.79			7-17-61	Paid by WHT#72 8 77
6-12-61	Labor 12.34	134.85		7-17-61	" " " #71 99
	10% O.H. 13.49		148.34	7-17-61	" " " #73 3 35
	78' 6" Transite pipe @.78		60.84	7-19-61	" " S#65 4 39
	14 Ton Fill .70		9.80	7-21-61	Paid 72 10
	1 6" Clay Elbow		1.88		289 60
	1 11 $\frac{1}{2}$ " Elbow Transite		2.24		
	7 Hrs. Town Shovel @6.50		45.50		
	3 Hrs. Trucking @3.00		9.00		
	12 x 3 Patch		12.00		
			<u>289.60</u>		
Bill sent 2-17-61 72.10					

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street.                      Work completed .....

Remarks: .....

.....

.....