

Name Tony Clough

Service No. 166 - 181

Address 89 Hancock Street

Location

Kind of Pipe

Size

Size of Main

~~Repair-Renewal~~ ~~XXXXXX~~ ~~XXXXXX~~ W. O. # 249

Location MAY 29 1973

Date	Material	Amount		Total	Date	Location	Amount
11/7/72	Labor	65	44		11-3-73	<i>Deposit Returned</i>	150
11/10/72	"	36	88		11-28-73		150
	10% O.H.	10	23	112	5-29-73		83
1	10'-6" Transite pipe .90			9		OUTSIDE	44
1	5'-6" Transite N. w/cplg	6	28	6	11/7/72	Labor	65
1	6"x6" Wye	9	37	9		"	44
1	3'x6" N. w/cplg	4	48	4	11/10/	"	36
1	2'x6" N. w/cplg	3	58	3		"	88
1	2'x6" Clay nipple	2	90	2	11/11	"	41
					11/16	"	20
1	1'x6" Trans N. w/cplg	2	68	2	20'	6" Transite .90	18
1	Duplex cplg.	2	72	2	1	5'6" N. w/cplg.	6
1/2	Bag cement	1	98	99	1	300 Sweep	8
1	6" Cap			2	3	Yd. Loadm	50
				38		Hrs. Truck 3.00	9
2 1/2	Hrs. Hired shovel	15.00		37	2 1/2	Hrs. Hired shovel	50
2	Hrs. Trucking	3.00		6	1	Hr. Truck	3
3	Lbs. Seed	1.10		3	2	" " 1.50	3
1	Yd. Loam			3	1	" Loader	4
				50	1 1/2	" Compressor 4.00	2
				50	1 1/2	" Roller	1
				25	1	" Shovel 4.00	4
							62
							271

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for a sketch of the service location.

Work completed

Street

Remarks: Original Service 5-7-45

Connection made in

.....  
.....  
.....  
.....