



Legend	
Manhole Inspection Status	Manhole Root Treatment
● Sewer Manhole Inspected	● 10-28
● Sewer Manhole (CNL)	● 11-24
● Sewer Manhole (Buried)	● 12-48
● Sewer Manhole (CNO)	
● Sewer Manhole	Manhole Cementitious Lining
PS Pump Station	● 10-28
○ Cap	● 11-24
	● 12-48
Sewer Television Inspection Status	Clean Inspect Test Seal
→ Sewer Pipe	→ 10-28
→ Sewer Pipe Televised	→ 11-24
→ Sewer Pipe Partially Televised	→ 12-48
→ Sewer Pipe No Television	
□ Sewer Basin	
Other Structural Rehabilitation	Manhole to Manhole Lining
● 10-28	→ 10-28
● 11-24	→ 11-24
● 12-48	→ 12-48
Rebuild Riser	Structural Short Liner
● 10-28 As-Built	→ 10-28
● 11-24 As-Built	→ 11-24
● 12-48 As-Built	→ 12-48
Raise Frame and Cover	Short Liners
● 10-28	→ 10-28
● 11-24	→ 11-24
● 12-48	→ 12-48
Manhole Encapsulation	Root Treatment
● 10-28	→ 10-28 As-Built
● 11-24	→ 11-24 As-Built
● 12-48	→ 12-48 As-Built



FIGURE 1

TOWN OF LEXINGTON, MASSACHUSETTS
PUBLIC WORKS DEPARTMENT

SEWER SYSTEM

Date: 10/31/2014 SCALE: NOTED

Weston & Sampson®