

Name **Martin Ward**

Service No. 262 N.D.

Address **378 Mass. Avenue**

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~Reconstruction~~ W.O. #477Location **MAR 14 1966**


Date	Material	Amount	Total	Date	Amount
-65	Labor	66.52		5/24/66	25 00
	10% C.H.	6.65	73.17	7-5-66	25 00
	10' 6" Transite pipe @.82		8.20	8-17-66	35 00
	1 22 $\frac{1}{2}$ " Transite band		4.09	9-8-66	26 97
	1 6" Nipple		.91		101 97
	$\frac{1}{2}$ bag cement @1.50		.75		
	1 22 $\frac{1}{2}$ " Transite Elbow		2.35		
	2 hrs. Town Truck @3.00		6.00		
	1 hr. Town Shovel @6.50		6.50		
			101.97		
				6-10-65	Roots
				9-18-64	Roots
				1-28-64	Roots
				1-18-64	Roots

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in ..... Street. Work completed .....

Remarks: *Original Service 10-26-38* .....

.....  
.....