

Name **Robert Tillinghast**

Service No. 98

Address **L65-475 Mass. Ave.**

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service W.O. # 6619

Location **SEP 22 1969**

Date	Material	Amount	Total	Date	Amount
7/31/69	Labor	102 03		10-11-68	1025 00
	10% O.H.	10 20	112 23	9-22-69	867 69
13'	8" Transite pipe	1.20	15 60		157 31
2	Ton 3/4" Stone @	1.65	3 30		
1/2	Bag Cement	1.55	78		
20	Brick @ .01 1/2		90		
1	Hr. Trucking		3 00		
1	" "		1 50		
4	" Compressor @	5.00	20 00		
			157 31		

*Disposal  
Returned*

