

Name **S. B. McGirr**  
 Address **582 Mass. Avenue**

Service No. **217**  
**1953**

**Location**

**Kind of Pipe**

**Size**

**Size of Main**

~~Repair~~ ~~Renewal~~ **New Service**

*Com. 6-1-54*

**Location**

Date	Material	Amount	Total	Date	Amount
4/26/54	Labor	45 06		12-28-53 Deposited	125 00
4/27/54	Labor	27 85		6-1-54 Refunded	(9 98)
		72 91			165 02
	10% Overhead	7 29	80 20		
	50' - 6" Sewer Pipe @ .3087		15 44		REPAIR W.O. #5163
	1 - 6" Elbow		1 88	7/22-24-25/67	Labor 222.89
	Joint Compound		3 00		10% O.H. 22.29
	6 hrs. Ltfld. Shovel @ 7.50		45 00	15'	6" transite pipe @.88
	2 hrs. Trucking		1 50	1	Bag Cement
	Patching 18x3		18 00	2	Doz. brick
			165 02	2	Ton Hot Top @5.80
				3	Hr. Shovel @ 6.50
				7	Hrs. Trucking @ 3.00
	<b>Labor</b>			1/2	Hr. Roller @ 3.00
					346 03

