

Mrs. Mabel Lanman

Service No. 61-A

Address 926 Massachusetts Avenue

Lexington

Location 926 Massachusetts Avenue

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

Com. 11-6-50

Location

Date	Material	Amount	Total	Date	Amount
14 '50	Labor	30 92		Aug. 15 '50	100 00
15 "	Labor	10 03		4-4-57	10 91
	10% Overhead	4 10	45 05		110 91
	70' - 6" Sewer Pipe		19 60		
	1 - 6" Elbow		1 56		
	Joint Compound		4 20	Bill sent 11-15-50	
	4 hrs. Littlefield Shovel		28 00	" " 3-7-52	
	2 hrs. Trucking		1 50		
	Patching 11 x 3		11 00		
			\$110 91		
	Labor				

