

Name William Wilson

Service No. 80

Address 103 Merriam Street

Lexington, Mass.

Location 103 Merriam Street

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair~~ ~~Renewal~~ New Service

Com. 12-19-49

Location

Date	Material	Amount	Total	Date	Amount
Oct 9, '49	Labor	53 00		Oct 20 '49	128 00
Oct 10, '49	Labor	10 73	63 73	Dec 31 '49	36 32
	10% Overhead		6 37		138 68
	64' - 6" Sewer Pipe @.265		16 96		
	Joint Compound		5 12		
	Littlefield Shovel 5 hrs. @7.00		35 00		
	Trucking 2 hrs. @.75		1 50		
	Patching 10 x 3		10 00		
			138 68		
	Labor				

