



Address	Map and Lot	Permit Number	Contractor Name	Inspector
83 Meriam St	63-43	6341	Arlex Oil Corporation	msprague
Date	Material	Depth of Cover	Amount	
9/16/2015	6"x6" PVC to AC Fernco	8 ft	1	
	6" PVC Pipe - SDR 35		9.5 ft	
	22° PVC Bend		1	
	6" PVC Pipe - SDR 35		68 ft	
	6" Cleanout with 22° Bend		1	
Type of work completed				

New 6" PVC sewer service installed to new house, connection to main.