

Name Donna Realty Trust

Service No. 46

Address 66 Middle Street

66 Middle ST.

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair~~ — New Service W.O. #4623 Valeri #576

Location JAN 22 1968

Date	Material	Amount	Total	Date	Amount
5-7-67	42' 6" Transite pipe			5-16-67	Deposit 150.00
	10' 4" Cast Iron pipe				
-16 67	Labor 113.31			5-8-67	
-8-67	" 21.24	134	55	20' 6" Transite	
	10% O.H.	13	46	1 6" Nipple	
	20' 6" Transite pipe @.88		17	1 6"-90° Elbow	
	1 8x6 Saddle		5	1 6" X 8" Wye	
	1 6" Nipple				
	1 90° Elbow		4		
	3 Load Stone		6		
	1 Load Gravel		8		
	4 Hrs. Trucking @3.00		12		
	3 Hrs. Shovel @6.50		19		
	1 Hr. Compressor @5.00		5		
	1 Hr. Roller @3.00		3		
			238		
			79		Bill out 28.29

