

Service No.

Address 60 Oak St.

60 OAK ST.

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair ~~XXXXXXXXXXXX~~ W.O. 5882

Location


Date	Material	Amount	Total	Date	Amount
11-10-77	20' 6" Transite				
	1 5' X 6" Nipple				
	1 6" - 45° Bend				
	1 4" DONUT				
				11/9/77	
					OUTSIDE
					Labor
					287 40
				20'	6" Transite @ 1.50
					30 00
				1	5' Nipple @ 1.75
					8 75
				1	3' Nipple
					8 70
				1	2' Nipple
					5 60
				19'	3/4 Copper @ .83
					15 77
				1	Box & Rod
					13 40
				8	Yds. Gravel @ 4.50
					36 00
				12	White Bricks @ .09
					1 08
				2	Ton Cold Patch @ 13.25
					26 50
				6	Hrs. Trucking @ 3.00
					18 00
				3	Hrs. Backhoe @ 6.50
					19 50
					Hot Top 20' x 5'
					64 90
					531 90

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks: Original Service 11-6-52 (50'-6" Sewer Pipe.)