

New Iceland Const. Co.

Service No. 171

Address 29 Oxbow Road

29 Oxbow Rd.

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~REPAIR~~ New Service

Location *Line 12-31-59*


Date	Material	Amount	Total	Date	Amount
-59	Labor	8 11		9-14-59	150 00
	10% O. H.	81	8 92	9-31-59	69 51
26'	6" Transite pipe @.75		18 20		80 49
1	22 1/2" Elbow		2 24		
1	Hr. Trucking		75		
			30 11		
	BILL WHEN CONNECTED				
-6-59	Labor	20.38			
	10% O. H.	2.04	22.42		
30'	6" Transite pipe @.70		21.00		
1	22 1/2" Transite Bend		6.21		
1	hr. Trucking @.75		.75		
			80.49		

DATE

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in

Street

Work completed

Remarks: