

Name David R. Spencer

Service No. 23

Address #23 Portside Ad.

JUN 18 1973

Location

Kind of Pipe *Transite*

Size *6"*

Size of Main *8"*

~~REPAIR SERVICE~~ — New Service J. M. Lucente #2303

Location

Date		Material	Amount	Total	Date	Amount
<del>1972</del>	<del>4-5-73</del>	<del>6" transite @ 2.50</del>	<del>187 50</del>		<del>4-5-73</del>	<del>187 50</del>
4-6-73	49'	6" transite				
					1972	
					26' 6" Transite	
					1 6"x8" Wye	

