

Name Moore Homes, Inc.

Service No. 104

Address 57 Paul Revere Rd.

JUN 20 1977

57 Paul Revere Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~REPLACEMENT~~ New Service DeFlice Bros. #2892

Location


Date	Material	Amount	Total	Date	Amount
/76	Labor	81. 04		12-7-76	Deposit 450. 00
	10%OH	8. 10	89. 14	6-20-77	Refund 36. 38
	30' 6" transite pipe @ 1.75		52. 50	12-15-76	363. 07
	1 6" nipple		2. 05		30' 6" Transite
	1 6" X 90° Elbow		6. 56		1 6" Nipple
	1 6" end cap		3. 80		1 6"-90° Elbow
	1 6 X 8 saddle		20. 42		1 6" X 8" Wye
2	ton cold patch @ 12.50		25. 00		
	Hot Top Sidewalk 5' X 13'		43. 32		
	Hot Top Street 8' X 19'		101. 28		
2	hrs. shovel @ 6.50		13. 00		
2	hrs. trucking @ 3.00		6. 00		
			363. 07		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:

.....

.....