

Name Donald McCarthy

Service No. 55

Address 33 Prospect Hill Road

33 Prospect Hill Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~REPAIR~~ New Service

Location

Comm 7-5-60

Date	Material	Amount	Total	Date	Amount
4-28-60	Labor	47.10		4-28-60	200.00
	10 % O.H.	4.71	51 81	7-5-60	78 89
4-9-	6" Transite Pipe @ .70		34 30		121 11
2	Hrs. Town Shovel @ 6.50		13 00		
3	Hrs. Trucking @ 3.00		9 00		
1	Hr. Pump @ 1.00		1 00		
	12x3 Patch		12 00		
			121 11		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....