

Name Howard A. Daziel

Service No. 165

Address 66 Prospect Hill Road

66 Prospect Hill Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair—Renewal—~~New Service~~

W. O. # 246

Location FEB 12 1973

Date	Material	Amount	Total	Date	Amount
11/9/72	Labor	86 33		11/1/72	300 00
11/10	"	36 88		2/12/73	94 57
	10% O.H.	12 32	135 53		205 43
	<u>OUTSIDE</u>				
26'	6" Transite pipe .90		23 40	11/9/72	161 46
1	O Ring		2 65	11/16/	53 07
2	Yds. Loam 3.50		7 00	2	5'-6" Nipple w/c/ 9 00
6	Lbs. Seed 1.10		6 60	2	6" Couplings 1.18 3 56
1	Yd. Gravel		2 00	1	10'-6" Transite .90 9 00
2	Hrs. Trucking 3.00		6 00	1	11" Ell 3 95
1/2	" " 1.50		75	1	Bag cement 1 98
1	Hr. Shovel		6 50	5	Yds. Gravel 2.00 10 00
1	Hired shovel		6 50	2	Ton cold patch 8.00 16 00
			15 00	3	Hrs. hired machine 15.00 45 00
			205 43	1	Hr. Shovel 4 00
				1 1/2	Hrs. Compressor 3.00 4 50
				2 1/2	" Truck 1.50 2 25
				1 1/2	" " 1.50 2 25
					Roller 1 00
					332 07

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of approximately 20 columns and 25 rows of small squares, intended for drawing a sketch of sewer service.

Connection made in Street. Work completed

Remarks: *Original Service 10-30-51 (44'-6" Sewer Pipe)*

.....
.....