

Name **Anthony Ruggiero**

Service No. **121**

Address **19 Richard Road**

Lexington, Mass.

Location **19 Richard Road**

Kind of Pipe

Size **6"**

Size of Main **8"**

~~Repair~~ **New Service**

Location

Date	Material	Amount	Total	Date	Amount
Nov. 13, '48	Labor	34 07	34 07	Oct 22 '48	125 00
	10% Overhead		3 41	Dec. 31 '48	38 68
	38' - 6" Sewer Pipe @.26		9 88		86 42
	1 - 6" 1/8 Bend		1 28		
	Joint Compound		2 28		
	Shovel 2 hrs. @ 7.00		14 00		
	Trucking 2 hrs. @.75		1 50		
	Patching 20 x 3		20 00		
			86 42		
	Labor				

