

Name John Busa

Service No. 681

Address 40 Rindge Avenue

Lexington, Mass.

Location 40 Rindge Avenue

Kind of Pipe

Size 6"

Size of Main 8"

Repair ~~Renewal~~ New Service

Com. 10-10-49

Location

Date		Material	Amount	Total	Date	Amount
Aug. 31, '49		Labor	36 50	36 50	Aug 8 '49	110 00
		10% Overhead		3 65	Oct 13 '49	20 35
		40' - 6" Sewer Pipe @.265		10 60		89 65
		Joint Compound		2 40		
		Littlefield Shovel 5 hrs. @7.00		35 00		
		Trucking 2 hrs. @.75		1 50		
				89 65		
		Labor				

*Deposited*  
*6/13/49*

