

Name Antonio Cataldo

Service No. 51

Address 47 Rindge Avenue

Lexington, Mass.

Location 47 Rindge Avenue

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair~~ ~~Renewal~~ - New Service

Com. 11-14-49

Location

Date	Material	Amount	Total	Date	Amount
Jul. 20, '49	Labor	11 50		July 16 '49	100 00
Jul. 21, '49	Labor	39 43		Nov 17 '49	1 16
Jul. 22, '49	Labor	18 00	68 93		98 84
	10% Overhead		6 89		
	40' - 6" Sewer Pipe @.265		10 60		
	1 - 6" - 1/8 Bend		1 52		
	Joint Compound		2 40		
	Littlefield Shovel 1 hr. @7.00		7 00		
	Trucking 2 hrs. @.75		1 50		
			98 84		
	Labor				

