

Name Leeland Construction

Service No. 91

Address 8 Ross Road Lexington 73, Massachusetts

8 Ross Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair~~ New Service

Location Comm 11-9-59

Date	Material	Amount	Total	Date	Amount
8/7/58	30' 6" Transite @ 70		21 00	6-17-59	Deposit 125 00
	1 6" Clay Elbow		1 88	11-9-59	* Refund 17 41
			22 88		107 59
Installed by contractor Bill when connected					
3-3-59	Labor	36.24			
	10% O.H.	3.62	39.86		
	37' 6" Transite pipe @.70		25.90		
	1 22 $\frac{1}{2}$ ^o Transite Bend		6.21		
	1 11 $\frac{1}{4}$ ^o Transite Elbow		2.24		
	2 hrs. Pippin Shovel @4.50		9.00		
	2 hrs. Trucking @.75		1.50		
	Labor		107.59		
				* Apply to W.H.C. #120	3.98
				* " " " #131	13.43

