



Address	Map and Lot	Permit Number	Contractor Name	Inspector
11 Rumford Rd	54-121	5812	Santo, David Gen'l Contr., Inc.	dpavlik msprague
Date	Material	Depth of Cover	Amount	
9/15/2014	6x6 AC to PVC Fern Co	7 ft	1-Connect to existing stub	
	6" PVC Pipe - SDR 35	7 ft	7 ft to Wye	
	PVC Wye	7 ft	1	
	6" PVC Pipe - SDR 35	7 ft	11 ft to 22 degree bend	
	22 degree PVC Bend		1	
	6" PVC Pipe - SDR 35		62 ft to HSE	
Type of work completed				
New sewer connection-septic abandonment				