

Name Joseph Bymbaca

Service No. 124

Address 39 Saddle Club Road

39 Saddle Club Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service W. O. # 57

Location DEC 18 1972

Date	Material	Amount	Total	Date	Amount
9/20/72	Labor	160 72		9-7-72	300 00
9/22/	"	45 58		12-12-72	24 30
	10% O.H.	20 63	226 93		324 30
	30' 6" Transite pipe .90		27 00		
	1 6" Cap		2 38		
	½ Bag cement 1.98		99		
	1 Ton cold patch		8 00		
	2 Ton hot top 8.00		16 00		
	4 Hrs. Trucking 3.00		12 00		
	3 Hrs. Shovel 6.50		19 50		
	1 Hr. Compressor		5 00		
	½ Hr. Loader 5.00		2 50		
	1 Hr. Roller		2 00		
	Trailer		2 00		
			324 30		

Deposit
Paid by W/O # 57

