

Name

Service No.

Address

22 Sherburne Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair—Renewal—New Service

Location

Date	Material	Amount	Total	Date	Amount
5-4-59	Outside				
	55' 6" Transite				
	1 6"-22½° Bend			12-23-99	
	1 6" Clay Elbow				Service Blocked 110' probably at chimney - respond
5-28-68	Inside				
	58' 4" C. I.				
	21' 3" C. I.				
	DAVE SANTO				
8/20/99	4" PVC				
	2 4x6 FERRO				
	52' 6" PVC				
	1 22° BEND				
	2 6" WYE COUPLERS				

