

Name Mrs. Walter Johnston

Service No. 107

Address 139 Simonds Road

139 Simonds Road

Location

Kind of Pipe COM. 8-30-54

Size 6"

Size of Main 8"

Repair—Renewal—New Service

SERVICE WAS IN TO CURB:

Location

Date	Material	Amount	Total	Date	Amount
7/1/54	Labor	20 62		6-28-54 Deposited	150 00
7/2/54	Labor	47 67		8-30-54 Refunded	(10 87)
	10% Overhead	6 83	75 12	9-4-52	139 13
	16'-6" Sewer Pipe @ .30		13 80	10' 6" Transite	
	Joint Compound		2 76		
	2 Hrs. Town Shovel @ 5.00		10 00		
	2 Hrs. Trucking @ .75		1 50		
			103 18		
	Plus attached card		35 95		
	Total charge:		139 13		
	Labor				

