

Name **Alfred Marciano**

Service No. 118

Address **20 Simonds Road****Lexington, Mass.**Location **20 Simonds Road**

Kind of Pipe

Size **6"**Size of Main **8"**~~Repair~~ **New Service**Com. **12-31-50**

Location

Date	Material	Amount	Total	Date	Amount
Dec. 19, '50	Labor	30 33	30 33	Oct. 25 '50	125 00
	10% Overhead		3 03		3 14
	50' - 6" Sewer Pipe		14 00		86 86
	Joint Compound		3 00		
	Littlefield Shovel 3 hrs. @.75	2 25	21 00	Dec. 19, '50	12 83
	Trucking 2 hrs. @.75	1 50	1 50	24' - 6" Sewer Pipe	6 72
	Patching 1/4 x 3		14 00	Joint Compound	1 44
			86 86	Littlefield Shovel 2 2/3 hrs.	18 67
				Trucking 2 hrs. @.75	1 50
				Sewer Brick	17 55
				Cement 4 bags	4 40
				1 - M. H. Cover & Frame	23 92
				Patching 1/4 x 3	14 00
	Labor				101 03

