

Name John F. Warner, Jr.

Service No. 131

Address 74 Simonds Road

74 Simonds Road

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair~~ ~~Renewal~~ ~~New Service~~ W.O. #3450

Location SEP 5 1967


Date	Material	Amount	Total	Date	Amount
10/24/66	Labor	39.57		10-14-66	87.00
10/25/66	Labor	<u>52.76</u>	92.33	2-14-69	<u>16.97</u>
	10% O.H.	9.23	101.56		103.97
20'	6" Transite pipe @ .88		17.60		
3	Hrs. Trucking @ 3.00		9.00		
3	Hrs. Loader @ 4.00		12.00		
2	Hrs. Shovel @ 6.50		13.00		
51'	6" Transite pipe @ .88		44.88		
1	Yd. Loam		3.00		
			<u>201.04</u>		
	PROVATED	<u>201.04</u> X	<u>12.11</u> =		
		25	103.97		
				4-5-1990	Johns Sewer - 66' out From outside C.O.
					Respond + MEASURE JW
				5-10-93	Roots 60' out from M-H in
					driveaway - Respond - town property
					Bill sent 16.?? can use Myers

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks: *Original Service 11-18-53 (70'-6" Sewer Pipe)*

.....
.....