

Name Anthony S. Messina

Service No. 32

Address 110 Spring Street

110 Spring ST.

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair - Renewal~~ New Service W.O.#6473 Trebino #6473

Location SEP 25 1978

Date	Material	Amount	Total	Date	Amount
8-7-78	Labor	165.00		7-14-78	285.00
	10% O.H.	16.50	181.50	10-25-78	29.59
	20' 6" Transite pipe @1.50		30.00		364.59
	1 6" Nipple		1.93		
	1 6" 90° Elbow		6.21		
	1 6" Transite Adapter		4.83		
	1 6" Transite Cap		4.12		
	2 ton Cold Patch @14.75		29.50		
	3 hrs. Trucking @3.00		9.00		
	3 hrs. Town Shovel @6.50		19.50		
	13' x 9' Patch		78.00		
			364.59		
3/28/78	22' of 6" ACP				
	10' of 4" CF				

