

Name Mrs. John Fernberger

Service No. 115

Address 50 Spring Street

50 Spring ST.

Location

Kind of Pipe

Size 6"

Size of Main 8"

~~Repair - Renewal~~ - New Service

com. 8-15-55

Location

| Date | Material | Amount | Total | Date | Amount |
|---------|---|--------|--------|---------|------------------|
| 6/30/55 | Labor | 50 50 | | 6-9-55 | Deposited 175 00 |
| 7/1/55 | Labor | 20 20 | | 8-15-55 | Refunded 31 59 |
| | | 70 70 | | | 143 41 |
| | 10% Overhead | 7 07 | 77 77 | | |
| | 52'-6" Sewer Pipe @ .32 | | 16 64 | | |
| | 1-6" Elbow | | 1 88 | | |
| | Joint Compound | | 3 12 | | |
| | 5-2/3 hrs. Littlefield Shovel @ 7.50-42 | | 50 | | |
| | 2 hrs. trucking @ .75 | | 1 50 | | |
| | | | 143 41 | | |
| | Labor | | | | |

