

Name Ernest Done

Service No. 98

Address 82 Spring Street

82 Spring ST.

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair or Renewal - New Service

com. 8-15-55

Location

Date	Material	Amount	Total	Date	Amount
5/26/55	Labor	101 83		5-23-55	Deposited 175 00
	10% overhead	10 18	112 01	8-15-55	Refunded (16 41
	66' - 6" sewer pipe @ .32		21 12		158 59
	joint compound		3 96		
	4 hrs. town shovel @ 5.00		20 00		
	2 hrs. trucking @ .75		1 50		
			158 59		
	Labor				

