

Name

Service No.

Address

22 Stimpston Avenue

22 STIMSON Ave.

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair—Renewal—New Service

Location

Date	Material	Amount	Total	Date	Amount
------	----------	--------	-------	------	--------

Rod Out Every 6 Months

Per William Hadley 4/8/91

4-8-91

Rod out

MIKE HENLEY

7-16-90

Bad pitch in service

7-28-91

S.B

8-1-91

S.P. No Pitch

8-7-90

No Pitch - Pipe may be broken

8-22-91

S.B. Repair

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street.                      Work completed .....

Remarks: .....  
.....  
.....