

Name Michael Cerula

Service No. 134

Address 34 Taft Avenue

34 Taft Ave.

Location

Kind of Pipe COM. 8-31-53

Size 6"

Size of Main 8"

~~Repair/Removal~~ New Service

Location

Date	Material	Amount	Total	Date	Amount
8/3/53	Labor	25 67		7-8-53	Deposited 175 00
	10% overhead	2 57	28 24	8-31-53	* Refunded (59 76)
	60' - 5" transite pipe @ .55		33 00		115 24
	5 hrs. Littlefield shovel @ 7.50		37 50		
	2 hrs. trucking @ .75		1 50		
	patching 15 x 3		15 00		* 2.37 made payable to
			<u>115 24</u>		Turn in Lip to apply
					on bal. due on m.A.C. #188
	Labor				

