

Name Mrs. Ann J. Wright

Service No. 23 923

Address 18 Tarbell Ave.

18 Tarbell Ave.

Location 18 Tarbell Ave.

Kind of Pipe

Size 6"

Size of Main 8"

Repair - Renewal - New Service

Location

| Date                             | Material                   | Amount   | Total | Date                  | Amount |
|----------------------------------|----------------------------|----------|-------|-----------------------|--------|
| 0/19/34-24                       | 6" Sewer Pipe @.27         | 6 48     |       |                       |        |
| om. 11-27-34<br>15-40<br>Russell | 10' 4" Iron Pipe @.75      | 7 50     |       | Oct. 16 1934 - Repair | 60 -   |
|                                  | Sulphur & Jute<br>Trucking | 96<br>75 | 15 69 |                       |        |
| 32                               | Hrs. Labor @.55            | 17 60    |       |                       |        |
| 37                               | " " @.50                   | 18 50    | 36 10 |                       |        |
|                                  | 10% Overhead               |          | 3 61  |                       |        |
|                                  |                            |          | 55 40 |                       |        |
| Nov. 27 1934                     | Refund                     |          | 4 60  |                       |        |
|                                  |                            |          | 60 -  |                       |        |
|                                  | Labor                      |          |       |                       |        |

