

Name William Sullivan

Service No. 219

Address 59 Tarbell Avenue

59 Tarbell Ave

Location

Comm. 12/31/57

Kind of Pipe

Size 6"

Size of Main 8"

Repair—Renewal—New Service

Location

Date	Material	Amount	Total	Date	Amount
11/22/57	Labor	7 14		11-19-57	Deposit \$ 100 00
11/23/57	"	49 63		1-30-58	Paid by ref. on W. A. O. # 273 25 62
		56 77			
	10% overhead	5 68	62 45	3-17-58	Paid 16 45
	64' - 6" Transite Pipe @ .70		44 80		\$ 142 07
	2 - 11 $\frac{1}{4}$ " ⁰ Transite Bends @ 5.10		10 20		
	4' - 6" Clay pipe @ .435		1 74		
	1 - 6" Clay Elbow		1 88		
	3 hrs. Town Shovel @ 6.50		19 50		
	2 hrs. Trucking @ .75		1 50		
			142 07		
	Labor				
					Bill sent 1-13-58
					\$ 16.45

