

Name G. Laurie Wallace

Service No. #23

Address 21 Vaille Avenue

21 Vaille Avenue

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair—Renewal—New Service

WO #7120

Location

Comm 6-25-62

Date	Material	Amount	Total	Date	Amount	
-16-62	Labor	57.06		4-6-62	Deposit	250.00
-17-62	"	48.74	105.80	4-25-62	Refund	17.28
	10% O.H.	10.58	116.38			232.22
68	6" Transite Pipe @.78		53.04			
1	90° Transite Elbow		5.40			
2	22½° Transite Bends @6.21		12.42			
2	11½° Transite Elbow @2.24		4.48			
12	X 3 Patch		12.00			
4	Hrs. Trucking @3.00		12.00			
3	Hrs. Town Shovel @5.50		16.50			
			232.22			

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of approximately 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....