

16.71 Name **Mrs. Thomas P. Rudd** Service No. **30**
 Address **14 Valley Road**
Lexington 14 Valley Road Location
 Kind of Pipe _____ Size **6"** Size of Main **8"**
~~Repair~~ **New Service** COM. **6-16-52** Location _____

Date	Material	Amount	Total	Date	Amount
4/21/52	Labor	66 39		4-7-52 Deposited	125 00
	10% overhead	6 54	71 93	6-16-52 Refunded	(16 71)
	32' - 6" sewer pipe @ .342		10 94		108 29
	joint compound		1 92		
	2 hrs. town shovel @ 5.00		10 00		
	2 hrs. trucking		1 50	1-20-48 Blockage 25' up from M.H.	
	patching 12 x 3		12 00	Service can be flushed from	
			108 29	M.H.	
	Labor				

