

Name

Frederick Cerullo

Service No. 69

Address

446 Waltham Street

Lexington **946 Waltham ST.** Location 446 Waltham Street

Kind of Pipe

Size **6"**Size of Main **8"**~~Repair~~ ~~Renewal~~ New Service

Com. 11-6-50

Location

Date		Material	Amount	Total	Date	Amount
t. 3	'50	Labor	38 57		Aug 27 '50	150 —
4	"	"	10 00		Nov 16 '50	3 79
		10% Overhead	4 86	53 43		121 21
		48' - 6" Sewer Pipe		11 76		Non-Charge
		Joint Compound		2 52	Oct. 4 '50	Labor 7 80
		5 hrs. Littlefield Shovel		35 00		8' - 6" Sewer Pipe 2 24
		2 hrs. Trucking		1 50		Joint Compound 7 00
		Patching 17 x 3		17 00		2 hrs. Littlefield Shovel
				121 21		Patching 8 x 3 8 00
					11-4-57	32 52
						20' 6" Clay Pipe
		Labor				

