

Service No.

Address 456 Waltham St.

456 Waltham Street

Location

Kind of Pipe

Size 6"

Size of Main 8"

Repair ~~XXXXXXXXXXXXXXXXXXXX~~

W.O. 5850

Location


Date		Material	Amount	Total	Date	Amount
11-1-	50	50' 6" Sewer Pipe				
					10/26/77	
						OUTSIDE
						Labor 191 60
						Police Duty 42 00
					1	6" x 2' Nipple 5 60
					1	6" Clay to Transite Adapter 4 80
					50	White Brick @ .09 4 50
					1	Bag Cement 3 25
					1	Yd. Gravel 2 44
					2	Ton Cold Patch @ 13.25 26 50
					2½	Hrs. Trucking @ 3.00 7 50
					2	Hrs. Backhoe 13 00
						Hot Top 10' # 6' 40 02
						341 21
					3-22-77	ROOTS
					2-7-77	SOLIDS
					7-11-77	700 #

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**SEWER DIVISION**

**DATE**

**Sketch of Service Here**



**Connection made in**

**Street**

**Work completed**

**Remarks:**