

Name **Firooz Rufe**

Service No. **186**

Address **20 Wheeler Road**

**20 Wheeler Road**

Location

Kind of Pipe

Size **6"**

Size of Main **8"**

Repair—~~Renewal~~ **New Service**

W. O. # **354**

**NO CHARGE**

Location **MAY 29 1973**


| Date    | Material                | Amount | Total         | Date    | Amount         |
|---------|-------------------------|--------|---------------|---------|----------------|
| 12/4/72 | Labor                   | 35 81  |               | 12-5-72 | Deposit 100 00 |
| 12/6/72 | "                       | 40 38  | 76 19         | 5-29-73 | Retard 100 00  |
|         | 6' 6" Akron pipe .90    |        | 5 40          |         |                |
|         | 1 Bag cement            |        | 1 98          |         |                |
|         | 3 Ton 1 1/2" Stone 3.00 |        | 9 00          |         |                |
|         | 2 Hrs. Shovel 6.50      |        | 13 00         |         |                |
|         | 2 Hrs. Stack 3.00       |        | 6 00          |         |                |
|         |                         |        | <u>111 57</u> |         |                |

DATE

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in ..... Street. Work completed .....

Remarks: *Original Service 1954 (85' installed by developer)* .....

.....  
.....