				क्षात्र कार्यक्षेत्रक क्षात्रकार <mark>्य</mark>		s é i Subseque a <u>namero é a ne</u> s								
	Nac	me _	Harold Rycroft	·		· · ·		· .		Service	No.	9		
• • •	Add	rest	142 Woburn Street	·		<u></u>				·	- -	<u> </u>		
			Lexington, Mass	142 W	obe	urn S	Loc	ation 14	2 <b>T</b> o	burn Street	· · · · · · · · · · · · · · · · · · ·	·		
	Kin	d of	Pipe		- <del>,</del>	Size	<del></del>			Size of Mai	n			
	Жŧў	<b>M</b> CX	MildWil X New Service	20m. 7-3	-50			<u> </u>	. •	Location	· <del></del>			
Date		,	Material	Amount		Total		Date		0.		Amount		
May	12,	150	Labor	39	87			april	150	Disposeties	e	130	00 -	
May	13,	150	Labor	16	10	55	97	July 2	50	Refundant		.5	14	
			10% Overhead			5	60	0				124	86	
5277.	<del>.=.</del>	-* .*\;	461 - 6" Sewer Pi	pe 👺.28		_12	88	<u> </u>						
	^		1 - 6" Elbow	· · · · · · · · · · · · · · · · · · ·		1	15						1	
			Joint Compound			2	76							
			Littlefield Shove	1.5 hrs	. @7	.00 35	00							
			Trucking 2 hrs. @			1	50						l	
			Patching 10 x 3			10	00							
						124	86							
			Labor					12.284		Casts 30' to	35 /	nu d		
	_								<b>1</b>	1001 / 11 / 200				
									<b> </b>			<del></del>		
<del> </del>							ļ <del></del> -							
HP-711	9					1.7	<b></b>				<u> </u>	i tuu waasa		

## TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS

								•		-		VI.														_
DATE					• • • •	•												•						NO.		• • • •
The undersi Street and hereb Sewers, as now	y ag	ree	s to	com	ιρly	wit	h th	ne F	tules	and	d R	egul	atio	ns	gove	erni	ng									
Am't of estimate	\$									-		_											-			
Am't Paid \$																										
			•															٠.	<i>.</i>	٠.	 		 • • •		c	Owner
	······=	<del></del>	-	-	<del>-</del>	<del></del>			Sk	etch	of	Ser	vice	He	70						 		 	<del>:</del> -		
										~~~				•••												
			1																Ι		1	1				
								-									-	1	<u> </u> 			-			. •	
																			 	1	1					

Remarks: