

WATER SERVICE RECORD

6799

Name Carlton W. Batson

Service No. 98

Address 56 Adams Street

8727

Location

~~Repair - Renewal - New Service~~

Comm. 9/30/57

| Date | Material | Amount | Total | Date | Amount | |
|--------|-------------------------------------|--------|-------|---------|---------------------------------|----------|
| 6/4/57 | Labor | 2 04 | | 5-21-57 | Deposit | \$ 50 00 |
| | 10% overhead | 20 | 2 24 | 9-30-57 | Refund | 10 61 |
| | 69' - 3/4" Copper tubing @ .4228 | 29 17 | 29 17 | | NON CHARGE | \$ 39 39 |
| | 1 - 3/4" Cx 1/2 I.W.H. Stop & Waste | | 4 96 | | Labor | 1 76 |
| | 1 hr. Trucking | | 75 | | 8' - 3/4" Copper tubing @ .4228 | 3 38 |
| | 1 - 3/4" C. Union (3 part) | | 2 27 | | 1 - 3/4" C. Corp Cock | 4 64 |
| | | | 39 39 | | 1 - 3/4" C. Curb Cock | 5 94 |
| | | | | | 1 Box & Rbd | 4 62 |
| | | | | | 1 - 1/2 Straight tailpiece | 50 |
| | | | | | 1 - 1/2 Offset tailpiece | 50 |
| | | | | | | 21 34 |

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for a hand-drawn sketch of water service details.

Connection made in Street. Work completed

Remarks:
.....
.....