

David Burton

WATER SERVICE RECORD

#3676

#6584

Name Leeland Construction Company

Service No. 21

Address 14 Asbury Street

Location

~~Repair-Renewal~~ New Service

Comm. 8-6-56

Date	Material	Amount	Total	Date	Amount
3/14/56	Labor	26 60		2-28-56	Deposit \$ 75 00
	10% overhead	2 66	29 26	8-13-56	Paid 5 88
	23' - 3/4" Copper tubing @ .4850	11 16			NON CHARGE 80 88
	1 - 3/4Cx $\frac{1}{2}$ I.W.H. Stop & Waste	4 96		3/15/56	Labor 110 76
	2 hrs. trucking @ .75	1 50		3/16/56	" 31 04
	4 hrs. Littlefield Shovel @ 8.50	34 00			141 80
			80 88		
				27' - 3/4" Copper tubing @ .4850	13 10
				1 - 3/4 C. Corp Cock	4 34
				1 - 3/4 C. Curb Cock	5 94
				1 Box & Rod	4 62
				1 - $\frac{1}{2}$ Straight tailpiece	50
				1 - $\frac{1}{2}$ Offset tailpiece	50
				4 hrs. Littlefield Shovel @ 8.50	34 00
				9 hrs. Compressor @ 2.75	24 75
				3 hrs. trucking @ .75	2 25
				3 hrs. Allis-Chalmers @ 3.00	9 00
				1 hr. #21 Truck	3 00
				1 hr. trailer	3 00
				3 hrs. trucking @ .75	2 25
					249 05

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of approximately 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: .....  
.....  
.....