

WATER SERVICE RECORD

Name William Hamilton

Service No. 269

Address 50 Asbury Street

Location

~~Repair/Replacement~~ - New Service

Comm 10-3-59

Date	Material	Amount	Total	Date	Material	Amount
10-26-59	Labor	2 10		10-19-59	Deposit	50 00
	10% O. H.	21	2 31	10-31-59	Retard	23 58
	3/4" Copper Tubing @.42	18	48			27 92
1	3/4" Cx 1/2 I.M.H. Stop & Waste	5	88		NON CHARGE	
1	Hr. Trucking @.75		75	10-26-59	Labor	1 61
			27 42	23	3/4" Copper tubing @.42	9 66
				1	3/4" C Corp Cock	4 57
				1	3/4" C Curb Cock	5 98
				1	Box & Rod	5 00
				1	1/2 Straight Tail piece	50
				1	1/2 Offset Tail piece	50
						27 92

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 20 rows high, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: .....  
.....  
.....