

Name Site & Shelter  
 Address 28 Barberrry Road

Service No. 234

#1659  
 #6988

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

*Com. 12-3-51*

Location

Date	Material	Amount	Total	Date	Amount
11-2-51	Labor	1 65	1 65	<i>9-25-51</i>	<i>10 00</i>
	10% Overhead		17	<i>9-23-52</i>	<i>12 63</i>
	44'-3/4" Copper Tubing @.326		14 34		<i>22 63</i>
	1-3/4"Cx1/2" I.W.H. S&W		4 00	11-2-51	Labor 2 40
	1-3/4"Cx3/4" Union (3 pts)		1 72	24'-3/4" Copper Tubing @.326	7 82
	1 Hr. Trucking		75	1-3/4" C Corp Cock	4 33
	Total		22 63	1-3/4"Cx3/4" C Curb Cock	4 67
	Trench Dug By Owner			1- Box & Rod	4 68
	Pipe Supplied And Laid By Owner			1-1/2 Offset Tail Piece	50
	Labor			1-1/2 Straight Tail Piece	50
				1 Hr. Trucking	75
				Total	25 65

*Deposited  
Paid*

*bill sent 12-3-51*

